

Annexure D

BUILDING SAFETY CERTIFICATE

No. 07 /RED/NBC/2025-26

Dated: 23/04/2025

It is certified that the existing building **BALUNI PUBLIC SCHOOL**, (name of the building or premises) at ,
UNIT-3 ,C 123 MAUJA MOHAMMADPUR , SIKANDRA, AGRA (address) is having block(s)/Floor(s) as
per details below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3	-	-	-	-	-

The building is owned/occupied by **BALUNI PUBLIC SCHOOL**, (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the **EXECUTIVE ENGINEER RURAL ENGINEERING DEPARTMENT (UP.Govt)** (Name of Department/ Govt.) on 23-04-2025 (date of inspection) in the presence of **SHRI SAURAV SINGH** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 23-04-2025 for a period of 2 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Not Applicable
2. Not Applicable
3. Not Applicable
4. Not Applicable
5. Issued on 23-04-2025 at **Agra** by **RURAL ENGINEERING DEPARTMENT, AGRA**

Signature with Seal :


सहायक अभियन्ता
ग्रामीण अभियंत्रण विभाग
प्रखण्ड-आगरा

Name : **RADHA RAMAN SHARMA**
Designation : **ASSISTANT ENGINEER**
Name & Address of Department/ Office: **OFFICE OF EXECUTIVE ENGINEER**
RURAL ENGINEERING DEPARTMENT
DIVISION AGRA